

## Software Version: EasyBuilder Pro V6.03.01.468

### **Corrections**

### **EasyBuilder Pro**

- 1. [EBPro] Fixed an issue where compilation may fail when the project contains an error GIF file.
- 2. [EBPro] Disabled monopoly setting of the default window in project templates.
- **3.** [EBPro] Fixed an issue where certain project file settings may not be saved correctly.
- **4.** Fixed an issue where system registers relating to Device no Response window may be ineffective.
- **5.** [cMT] Fixed an issue where connection may not be established successfully due to the delayed reply from database server to ALTER command that occurs when using MariaDB 5.5.
- **6.** [cMT] Fixed an issue where a printer may be mistakenly displayed as installed when it is being re-installed after installation fails with error.
- **7.** Fixed an issue where macro functions StringInsert and FLOAT2ASCII cannot be executed properly.
- 8. Fixed an issue where certain calculations in macro may not be carried out correctly.
- **9.** [EasyConverter] Fixed potential DLL security vulnerabilities.
- 10. Fixed an issue where Modbus TCP/IP Server cannot properly access PLC data.
- **11.** [iE/XE/eMT] Fixed an issue where the elapsed time is incorrectly displayed in Event Display.
- **12.** [EBPro] Fixed an issue where slightly changing the position of the selected objects using the direction keys of the keyboard is not possible.
- **13.** [EBPro] Fixed an issue where "0 is short of space" message shows when opening Data Transfer settings.
- **14.** [EBPro] Fixed certain compilation issues relating to macros.

### **Drivers**

- 1. [Modbus] Fixed an issue where setting 0x /1x address range may start with an incorrect read address.
- 2. [OMRON EtherNet/IP (NJ/NX Series)] Fixed connection issue that occurs after disconnection.



3. [Beckhoff TwinCAT PLC – Free Tag Names (Ethernet)] Fixed an issue where compilation error may occur due to incorrect identification of Tag address type.



## **Supplementary Note**

From version 6.03.01.239 or later, [Siemens S7-1200/S7-1500 (Symbolic Addressing) (Ethernet)] driver is no longer applicable for iE/iP Series models.



# EasyBuilder Pro Release Notes

## **Software Version: EasyBuilder Pro V6.03.01.375**

#### **New Features**

1. MT8051iP, MT8071iP and MT8102iP: Added support for VNC Server.

### **Corrections**

### **EasyBuilder Pro**

- 1. [Backup] Fixed an issue where LB-9039 (status of file backup activity) is not set ON when backing up data to EasyPrinter.
- **2. [Window Copy]** Fixed an issue where the pictures in a window are not copied simultaneously when window copying from an earlier version of project file.
- **3.** [Data Sampling] Fixed an issue where [Set OFF after sampling finished] option is not canceled after changing from Trigger-based to Time-based mode.

#### Common

1. Fixed an issue where frequently writing same values to specific system reserved registers (LW-9134, LB-9019 and LB-9033) for a long period may cause system instability.

#### **cMT Series**

1. [Database Server] Fixed an issue where re-connecting to MS SQL Server frequently for a long period will stop data from updating.

#### cMT Viewer

1. Fixed an issue where pictures or texts appear blurry when in 1:1 ratio and either project screen width or height is smaller than that of cMT Viewer.

### **UtilityManager**

- 1. Added support for [cMT Server OS Update].
- **2. [EasyWatch]** Added MODBUS RTU (Zero-based Addressing) driver.
- **3.** [Serial Pass-Through] Fixed an issue where cMT Gateway's pass-through parameters cannot be correctly set.
- **4.** [Ethernet Pass-Through] Fixed an issue where Ethernet Pass-Through cannot be used when the default gateway IP address is not set on PC.
- 5. [Ethernet Pass-Through] Added support for using this feature on Gateway Series.



# EasyBuilder Pro Release Notes

### **Drivers**

- 1. [BACnet/IP Server] Added support for tags that shows server status and fixed disappeared Alarm objects.
- [Rockwell CompactLogix Free Tag Names] Added support for multi-dimensional array.
- 3. [Barcode Scanner/Keyboard] Expanded BARCODE address range.
- 4. [Bosch Rexroth SIS (Symbolic Addressing)] Added support for importing SYM file.
- 5. [FATEK FB/FBs/B1/B1z Series] Added support for T\_FBe, C\_FBe addresses.
- 6. [SAIA S-BUS (Ethernet)] Expanded Flag, Input, and Output address ranges.
- 7. [Siemens LOGO (Ethernet)] Added support for LOGO 0BA0 model.
- 8. [CODESYS V3 (Ethernet)] Added support for Toshiba Motorola Byte device.
- [LS XGK FEnet (Ethernet)] and [LS XGM/XBC Cnet] Expanded ranges of some addresses.
- 10. [Modbus TCP/IP] Fixed an issue where incorrect byte-swapping occurs when a value is mis-written to LW-10518.
- **11. [KOYO DIRECT]** Added support for cMT-G03 serial bridge.
- **12.** [motrona MC700] Added support for CODE\_Bit address.
- **13.** [PARKER SLVD Series] Fixed an issue where writing specific values to specific address will fail.
- **14.** [XINJE XC Series] Added support for cMT-G03 serial bridge and FD8000, FS, ID and QD addresses.
- 15. [Siemens S7-300/ET200S (Ethernet)] Expanded I, Q and M address ranges.
- **16.** [Siemens S7-1200/S7-1500 (Symbolic Addressing) (Ethernet)] Added support for importing tags from blocks under groups.
- 17. [Siemens S7-1200/S7-1500 (Symbolic Addressing) (Ethernet)] Fixed an issue where selecting a single tag in Tag Manager is ineffective.
- 18. [Weintek Built-in CODESYS], [CODESYS V3 (Ethernet)] and [Schneider SoMachine M Series (Ethernet)] Fixed data transfer issue of REAL array.



**Software Version**: EasyBuilder Pro V6.03.01.239

### **Corrections**

### **EasyBuilder Pro**

- 1. [Function Key] Fixed the problem where "Return to previous window" and "Close window" option cannot be saved properly.
- 2. Fixed an issue relating to incomplete rendering of BMP images in the editing screen.

### **Utility Manager**

1. Fixed an issue where a PC cannot establish connection for Ethernet Pass-through via WiFi.



## Software Version: EasyBuilder Pro V6.03.01.216


### **Supported Models**

4. Added support for cMT-iV6.

### **New Features**

### **EasyBuilder Pro**

1. Added support for bulk changing of security settings of multiple objects (by using the right-click menu).



**2.** Added support for bulk removing of shape, picture, and sound settings of multiple objects (by using the remove button in the toolbar).

#### **Common Features**

1. [Trend Display] Added "Relative time mode" option.

#### **cMT Series**

- 1. [MQTT] Added support for Azure IoT Hub cloud service.
- **2.** [Action Trigger] Improved operation experience; for example, it is now possible to change action order by drag-and-drop.
- **3.** [Action Trigger] Added "Check condition recursively when actions ended" option in Value Changed mode.
- 4. [Combo Button] [ASCII] Added support for designating a word address as condition



in Security settings.

- **5.** Added support for system registers relating to private address index: PLW-9200 ~ PLW-9215, PLW-9230 ~ PLW-9260.
- **6.** Added support for system register LW-9216: The result of importing email data.

#### **OPC UA Server**

1. Added support for import/export of information model tag file in XML format.

### **Utility Manager**

1. (cMT Series) Added the Ethernet Pass-through tool. The HMI used for Ethernet Pass-through must be using the runtime from this version or later ones.



Ethernet Pass-through
Connect to a network device on another
Ethernet port of HMI

#### cMT Viewer

- 1. (PC version) Added print screen feature, found in the right-click menu.
- 2. (Mobile version) Added support for hiding Start Button.
- **3.** Added support for monitoring non-visible objects for Diagnoser. Example objects include: Data Sampling, Event Log, PLC Control...etc.

### **Drivers**

- 1. [CODESYS V2 (Symbolic Addressing)] Added support for accessing the bits in a word tag.
- 2. [Siemens S7-1200/S7-1500 (Symbolic Addressing) (Ethernet)] Added new driver.
- 3. [SIKONETZ5] Added new driver.
- 4. [BACnet/IP] Added support for Alarm.